



Fire Extinguisher Servicing Price Guide

All prices listed in this guide are exclusive of VAT

Servicing Prices

Annual basic Service	£8.00
Fire Blanket Inspection	£2.00

Extended Servicing inc Recharge and Replacement

Every 5 years an extended service must be carried out on Water, Foam, Powder & Wet Chemical extinguishers, and 10 years for CO2.

This consists of the extinguishers been fully discharged to ensure good condition then refilled and recharged.

The prices are also the cost of attending to a discharged extinguisher.

Water with Additive Refill	£25.00
Water Refill	£14.00
Foam Refill	£27.00
Powder	Replace with new
CO2	Replace with new
3L Wet Chemical Refill	£55.00
6L Wet Chemical Refill	£76.00
Recharge Pressure Only	£19.99 call out fee.

On-site Extinguisher Commissioning and Installation

Commissioning	£5.00
Commissioning & Installation	£11.00

Site Visit Charge

A single site visit charge will be added to the job.

Site Visit Charge	£19.99
-------------------	--------